DATE RETURNED: 03/25/99 SERVICE ORDER S - 1331

DESCRIPTION OF REPAIRS DONE

REPLACED TRANSISTORS AND T.CAPICITOR
ON PLL UNIT.
ALIGNED & TESTED TO FACTORY SPECS

TOTAL PARTS:	8.99
SHOP LABOR:	232.75
FREIGHT:	36.00
TAX:	0.74
TOTAL:	278.48

DATE: 03/08/99

MAKE:	MODEL:	SERIAL#:	FIRST NAME:	LAST NAME:
KENWOOD	TS79DA	60300076	JIM	SADLER

ESTIMATE:	WARRANTY:	CONTRACT:	ADDRESS:
		Y	

PROBLEM: CITY: STATE:
LOCKED UP CA

HOME PHONE: WORK PHONE:
(415) 731-6475

ACCESSORIES SENT:
ORIGINAL BOX
1.2 MODULE

Ham Radio Outlet

MFG REF#: 281295 REPAIR COMPLETE: Y